


ADJUSTMENT OF THE SOFT-CLOSING DEVICE FOR SMART CORNER UNIT
AND PULL-OUT LARDER UNIT



In case the piston closes at the opening of the door (see above picture). This leads to an impossibility to close the door and a malfunction of the soft-closing device.



VIBO[®]
Wire processing



The piston must look like the above picture. Totally opened and locked in position, ready to get actioned as the door closes.



Headquarters:
Via Arzignano, 46, 36070 Trissino (VI) – Italy
T. +39 0445492800 F. +39 0445492999
P.I. 01265720241
vibo@viboitaly.com - www.viboitaly.com
Certificato n.ICILA-SGQ-000153



Chrome and epoxy plant
Via Majorana, 5
36075 Montecchio Maggiore (VI) – Italy
Certificato n.ICILA-SGA-209



VIBO[®]
Wire processing



You must adjust the level of the screw inside the highlighted arm. As you tighten the screw, the arm will go closer to the piston, allowing a better caught on it. As you unscrew, the arm will decrease, lowering the grip on the piston. Never totally fix the screw, this would lead to friction.



Headquarters:
Via Arzignano, 46, 36070 Trissino (VI) – Italy
T. +39 0445492800 F. +39 0445492999
P.I. 01265720241
vibo@viboitaly.com - www.viboitaly.com
Certificato n.ICILA-SGQ-000153



Chrome and epoxy plant
Via Majorana, 5
36075 Montecchio Maggiore (VI) – Italy
Certificato n.ICILA-SGA-209